

DPP with A/D

OFFICE OF THE SUPERINTENDING ENGINEER  
GHATAGAON(R&B) DIVISION, GHATAGAON-758027(ODISHA)

Email ID:- [eeghatagaon2015@gmail.com](mailto:eeghatagaon2015@gmail.com) phone No. 06733-299903

Letter. No. 2080 Dt. 27/4/2022

✓ To,

The Principal,  
Kendriya Vidyalaya, Anandapur.  
At/Po-Anandapur  
Dist-Keonjhar  
[Email-ld-kvandapur@gmail.com](mailto:Email-ld-kvandapur@gmail.com)

Sub: - Regarding Safety certificate of Kendriya Vidyalaya, Anandapur (functioning in side campus of Brajabandhu Bidyapitha, Anandapur).

Ref :- Your Letter No. 93 dt.16.02.2022.

Sir,

With reference to the subject & letter cited above, it is to state that, the Assistant Executive Engineer, (R&B) Sub-Division, Anandapur & Junior Engineer Anandapur Section-II jointly inspected the above school building on dt.24.04.2022 & found that the building is structurally safe in normal weather condition to use as school. The safety certificate is given as below.

"Certified that the Kendriya Vidyalaya, temporary functioning inside campus of Brajabandhu Vidyapitha at Anandapur is structurally safe in normal weather condition and can be used as school for teaching and other schooling activities.

This is for your information.


Yours Faithfully

  
27/4/22

Superintending Engineer  
Ghatagaon (R&B) Division

Memo No. 2081

Dt. 27/4/2022

  
27/4

Copy to the Assistant Executive Engineer Anandapur (R&B). Sub-division, Anandapur for information with reference to his Letter No.296 dt.26.04.2022.

  
27/4/22

Superintending Engineer  
Ghatagaon (R&B) Division

  
27/4